

## Epson P-40s

This printer may be used with many computer devices not sold by American Labor. However American Labor will not be responsible for making the printer work with your equipment. American Labor will furnish all necessary documentation to assist you.

### Specifications

Type:	Thermal dot matrix printer
Printing direction:	Uni-directional (left to right)
Printing speed:	40 column mode, 20 to 45 cps 80 column mode, 20 to 40 cps
Paper:	Thermal friction feed roll 4 3/8" wide 1 3/16" diameter 33 ft. or longer (average)
Print columns:	40 or 80 column
Character set:	ASCII (95 characters) 32 graphics characters
Port I/O:	RS-232C
Baud rates:	300, 1200, 2400, 4800 switch selectable
Hardware control:	DTR communications control (only)
Power supply:	NiCa battery pack / external AC adapter 110 VAC or 220 VAC must be ordered for proper voltage at time of order
Weight:	approx. 1.25 lbs.
Size:	8 1/2" wide x 5" deep x 1 9/16" high
Communications cable:	Must be ordered separately
Includes:	1 roll Epson thermal paper AC adapter for 110V AC Owners manual



AC adapter for 110 VAC operation included with printer unless otherwise specified at time of order.

Part # HOOAAA

Epson P-40 thermal roll paper  
4 3/8" wide 1 3/16" diameter  
33 ft. or longer (average)

Part # CDP-1



*Distributed in the USA by:*  
**American Labor**  
1308 Broad Street  
Durham, NC 27705

**Voice 919-286-0726**  
**Fax 919-286-3956**  
**Tech. 800-424-0443**  
**www.americanlabor.org**